


**Figure 1 -Measure Cocking Piece**

Two measurements need to be made:


A) Cocked with safety in "ON" or safe position.

B) Cocked with the safety in "OFF" or fire position.

Take measurements from the same location on the cocking piece and bolt shroud each time for accurate measurements. You are trying to establish a reference point.



**Figure 2 -Trigger Parts**



**Figure 3 -Hex Key Hole Location**

